



977 / 977LA Version 0 Stand-Alone Cleaner System (Serial Numbers 640725 and Below)

Background

ADT announces the formal discontinuation of the **977 / 977LA Version 0 Stand-Alone Cleaner system**, effective **May 30, 2020**. This discontinuation applies to all systems with **serial numbers 640725 and below**.

The discontinued Version 0 systems will be replaced by ADT's newly improved **977 / 977LA Robust Version Stand-Alone Cleaner system**, offering enhanced performance and reliability.

To support existing customers, ADT will provide a **seven-year support program** for all 977 / 977LA Version 0 systems. This program is designed to ensure continued operation by providing the necessary services and spare parts for as long as feasible.

Field Service Support

ADT will provide field service support for the **977/977LA Version 0 Stand-Alone Cleaner system** through **May 30, 2027**.

Support will include:

- Routine maintenance
- Repair services (subject to spare parts availability)

For questions regarding available service options for your 977 / 977LA system, contact regional or local ADT Representative staff or ADT Customer Support directly.

Spare Parts Support

ADT will continue to sell standard spare parts for the **977 / 977LA Version 0 systems** through **May 30, 2027**.

At its discretion, ADT may:

- Supply available spare parts from existing inventory
- Recommend and sell substitute parts or conversion kits when feasible

Please note that **spare part prices and lead times may increase after May 30, 2020**, due to reduced purchasing quantities.